

**PLEASE CHECK WWW.MOLEX.COM FOR LATEST PART INFORMATION**

**Part Number:** [64000-0075](#)  
**Status:** **Active**  
**Description:** Hand Tool Repair Kit

**Documents:**  
[RoHS Certificate of Compliance \(PDF\)](#)

**General**

Product Family	Application Tooling
Series	T0103
Comments	0192790160 (2 jaw return springs) 0192790168 (2 pivot pins) 0194110177 (4 rings, b.e.) 0192280397 (4 shims, .005") 0194110393 (4 rings, c.e.) 0192790107 (2 cam follower rods, 5.54mm dia.)
Function	Crimp
Geographic Area	Global
Level of Automation	Manual
More Detailed Tech Information	<a href="mailto:applicationtooling@molex.com">applicationtooling@molex.com</a>
Product Name	N/A
Survey	<a href="http://www.molex.com//review/apptool_survey.html">www.molex.com//review/apptool_survey.html</a>
Tool Type	Repair Kit

**Material Info**

**EU RoHS** **China RoHS**

**Compliance Status**

**Not Reviewed**

**REACH SVHC**

**Not Reviewed**

**Low-Halogen Status**

**Not Reviewed**

**Need more information on product environmental compliance?**

Email [productcompliance@molex.com](mailto:productcompliance@molex.com)  
For a multiple part number RoHS Certificate of Compliance, [click here](#)

Please visit the [Contact Us](#) section for any non-product compliance questions.

**Search Parts in this Series**

T0103Series

**PLEASE CHECK WWW.MOLEX.COM FOR LATEST PART INFORMATION**